## FORM B

SECTION 4(1)

[SEE RULE 7(II)]

## Form of Notice to be served for carrying out the directions of the Nominated Authority

SFO-17/2024/ 06

## NOTICE

Dated:-

I, Jagtar Singh Station Fire Officer, the Nominated Authority appointed under the Delhi Fire Prevention and Fire Safety Act. 1986, as extended to the Union Territory, Chandigarh, on the basis of inspection conducted this office on 28-12-2023 do hereby call upon you to undertake the Following Fire Prevention and Fire Safety Measures in Building/ Premises No SCO No.58-59, Sector 17/B, Bank Square, Chandigarh.

- Fire Extinguishers ISI Mark found not installed -
- First Aid Hose Reel found not installed 2
- Wet Riser found not installed
- 4 Yard Hydrants with Accessory in Box found not installed
- 5 Automatic Sprinkler System found not installed
- 6 Manually Operated Electronic Fire Alarm System found not installed
- 7 Automatic Detection and Alarm system found not installed
- 8 Underground Static Water Storage Tank capacity 100000 liter exclusively for Fire-fighting purpose found not installed
- 9 Terrace Tank over respective tower terrace capacity 10,000 Liter exclusively for Fire-fighting purpose found not installed
- 10 Provision of required number of sets of pumps each consisting of One Electric and One Diesel Pump (Standby) of capacity 2280 Liter per Minute and One Electric Pump of capacity 180 Liter per Minute found not installed.
- 11 Two-way installed instead of Four-way Fire brigade connection
- 12 Smoke Exhauster System in Basement Connected to Detection/Sprinkler System found not installed
- 13 Gong Beil connected with Sprinkler System found not installed
- 14. Public Address System found not installed.
- 15 Pressurization System in Internal Staircase, Lift Lobby & Fire Lift connected with Detection/Sprinkler System found not installed.
- Provision of at least C2 Exits at every floor.
- 17. Fire Check Doors found not installed
- 18 Fire Lift with Fireman Switch found not installed
- 19 Fire Command Centre at Ground Floor with Accessories found not provided
- 20 Illuminated Type EXIT Signboards at all escapes routes found not installed
- 21 Alternative Source of Electricity Supply found not installed
- 22 Emergency Lights in Staircase found not installed
- 23. All wooden compartmentation required to be removed or painted with fire resistance paint
- 24 Apply for the Fire Safety Certificate on below mentioned on below link on official website of MC Chandigarh -

http://mcchandigarh.gov.in/?q=fire-salety-certificate

06 01 ज्ञास प्रमुख/ZH एप अपल प्रमुख/DZM SEPLU /AGM FLTL/CM a.g/SM विसाम/Deptt.

Above action should be completed latest

by 01-03-2024

NOMINATED AUTHORITY

(Owner/Occupier)

To.

The Zonal Manager, Central Bank of India, SCO No.58-59, Sector-17/B,